



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
SUPERFUND SITE STRATEGY RECOMMENDATION - REGION 06



Site Name: Standard Brake Shoe and Foundry CERCLIS ID#: ARN000606789

Alias Site Names: _____

Address: 3200 Pullen Street

City/County or Parish/State/Zip Code: Pine Bluff, Jefferson County, Arkansas

Report Type, Date, and Author: Expanded Site Inspection (ESI), June 2009, ADEQ

RECOMMENDATION

<input checked="" type="checkbox"/> 1. No Further Remedial Action Planned under Superfund (NFRAP)	<input type="checkbox"/> 2. Further Investigation Needed Under Superfund
	<input type="checkbox"/> PA <input type="checkbox"/> HRS Priority: <input type="checkbox"/> High
	<input type="checkbox"/> SSI <input type="checkbox"/> RA <input type="checkbox"/> Medium
	<input type="checkbox"/> ESI <input type="checkbox"/> RI/FS <input type="checkbox"/> Low
	<input type="checkbox"/> Other: _____
	To be performed by: _____
<input type="checkbox"/> 3. Action Deferred to: <input type="checkbox"/> RCRA <input type="checkbox"/> NRC	

NOTIFY AUTHORITY:

<input type="checkbox"/> Removal	<input type="checkbox"/> RCRA	<input type="checkbox"/> TSCA	<input type="checkbox"/> CAA	<input type="checkbox"/> SMCRA
<input type="checkbox"/> Remedial	<input type="checkbox"/> State	<input type="checkbox"/> NPDES	<input type="checkbox"/> NRC	<input type="checkbox"/> Resource Trustee: _____
<input type="checkbox"/> CERCLA Enforcement	<input type="checkbox"/> Federal Facility	<input type="checkbox"/> UIC	<input type="checkbox"/> SPCC	<input type="checkbox"/> Other: _____
SEND SSSR COPIES TO:		<input checked="" type="checkbox"/> 6SF-AC	<input type="checkbox"/> 6WQ-SP	<input type="checkbox"/> ATSDR <input checked="" type="checkbox"/> State Agency <input type="checkbox"/> Other

DISCUSSION:

This inactive site covers a total of approximately 5.6 acres, and was used for casting and manufacturing of Brake Shoe. Former operations at the site involved the used of a foundry and other possible metal finishing operations. All equipment and machinery has been removed from the site and the building on-site is empty. The site is primarily covered with concrete and asphalt. Access to the site is restricted with a fence and locked gate.

Groundwater is used as a drinking water source; however, the drinking water aquifer is at a depth of 850 feet, making migration of contaminants the aquifer unlikely. No groundwater samples were collected for this investigation. There are no drinking water wells located on the property and no surface water intakes located downstream of the site. There are no schools or daycare centers located within 200 feet of the site. The likelihood of direct contact with contaminated soil is minimal because site access is restricted with a fence and locked gate. The air pathway is not a concern since there are no activities being conducted at the site.


A decision of "No Further Remedial Action Planned" (NFRAP) under Superfund will be entered in CERCLIS, and the site will be referred to the State.

Based upon currently available information, this site fails to meet the minimum criteria required to be included, or proposed, at this time on the NPL by the EPA. The NPL is EPA's list of sites that are priorities for further investigation and, if necessary, response action under CERCLA, 42 USC 960001 et seq. Other actions maybe appropriate under State Authorities.




APPROVALS:

Report Reviewed by: Philip Ofosu
(Site Assessment Manager 6SF-TR)

Signature: 

Date: Jul/28/09

Disposition Approved by: John Meyer
(Section Chief 6SF-TR)

Signature: 

Date: 7/28/09